



Blackleaf








Choteau



Dutton



Legend


Parcels

Condition, Desirability, and Usefulness of Residential Structures Null (216)

Unsound (3)


Very Poor (3)

- Poor (7)
- 🔲 Fair (28)
- Average (183)
- ____ Ilvelage (1
- Good (66)
- Very Good (38)
- Excellent (3)




Fairfield

Housing Condition




New Rockport Colony

Housing Condition



Pendroy





Housing Condition Source: Montana State Library Cadastral

14TH LN NE BOWAVE Parcels 3RD ST Condition, Desirability, and Usefulness of Residential 12. 🗆 Null (136) Unsound (o) Very Poor (0) Poor (5) Tethlune 🔲 Fair (7) Average (45) Good (7) Very Good (3) 0.7 Miles 0.175 0.35 Excellent (0) n